50's Style Wiring Toggle switch o C C C Braided Wire Solder External Shield to Pot Braided Wire Solder External Shield to Pot NECK VOL 500K Fold back on to the pot body and solder in place BRIDGE VOL 500K Fold back on to the pot body and solder in place NECK TONE 500K Connect to bridge post Fold back on to the pot body and solder in place BRIDGE S TONE 500K **JACK** = Solder Points

Humbucker Pickups wires vary and you may not have a braided core, The hot wire often red would go to the pins on the potentiometers and the ground wires go to the body of the potentiometers as the earth. If you are not sure, check you Humbuckers details